



coregas 

Shieldpro

and Coregas

shielding gases
troubleshooting

guide


Wesfarmers Energy
Coregas is part of Wesfarmers Energy

industrial gases

Coregas shielding gases

WELD FAULT

CRACKS

CAUSE	SOLUTION
Weld bead too small	Decrease travel speed
Poor fit up	Control joint tolerance
Lack of pre/post heat on alloy steels	Apply heat as advised by material supplier
High joint restraint	Modify design and/or application technique
Removal of torch before weld crater has solidified	Keep torch in position over molten crater until gas flow stops
Presence of grease, paint, foreign matter on work	Clean workpieces/ surfaces prior to welding
Excessive voltage	Reduce voltage so a faint 'crackle' can be heard in the arc
Welding over SMA tack welds	Completely remove all SMA slag and grind tacks

POROSITY

Insufficient gas coverage	Increase flow rate to afford effective shielding
Excessive flow rates	Reduce to max. 15 litres/min (spray transfer) 12 litres/min (short arc) If helium mixtures are being used, check and apply correction factors to flow rates
Spatter in nozzle	Clean gas nozzle
Ineffective gas shielding through draughts, winds etc.	Erect screens to protect weld area
Excessive stick-out distance	Maintain recommended torch-work distances
Inefficient gas hoses and/or connections	Check, replace and tighten as required
Excessive current and/or voltage	Adjust for optimum conditions

troubleshooting guide

WELD FAULT

CAUSE	SOLUTION
Contaminated or wet shielding gas	Use high purity Coregas and Shieldpro shielding gas mixture
Contaminated wire	Ensure wire is free from excessive drawing lubricant
Wrong wire analysis	Select to suit workpiece
Rust, oil, grease, paint or contaminants on work	Clean work prior to welding
Acute torch to work angle	Hold torch at 10° from vertical for downhand welding

SLAG INCLUSIONS

Excessive travel speeds where heavy oxides are present	Reduce travel speeds
Contaminants on work surface	Clean prior to welding
Lack of interpass cleaning	Remove slag deposits between passes
Weaving too wide	Reduce weave width. Use stringer passes.

INCOMPLETE FUSION

Voltage too low Weld pool too large	Increase voltage Increase travel speed. Reduce weave width.
Excessive wire protrusion	Maintain at 15–20mm (spray transfer) 7–10mm (short arc)
Misdirected wire	Direct wire carefully
Cold deposits	Increase voltage. Adjust inductance value (short arc).

INCOMPLETE PENETRATION

Poor joint design	Provide access to bottom of weld preparation
Inadequate butt joint root gap	Ensure adequate root gap
Weld pool too large	Increase travel speed.
Preparation too small	Increase preparation angle

WELD FAULT

CAUSE	SOLUTION
Incorrect torch angle	Maintain torch at 10° maximum to vertical
Excessive wire (protrusion)	Limit to 15–20mm range (spray transfer), 7–10mm range (short arc)
Excessive root face	Reduce root face
Current too low	Increase current (wire feed speed)
Poor current pick up	Check contact tip bore
Inefficient work return clamp	Attach efficiently. Clean workpiece before attaching

UNDERCUTTING

Torch angle too low	Raise torch angle
Travel speed too slow	Increase travel speed
Voltage too high	Lower voltage
Travel speed too fast	Reduce travel speed
Excessive current	Reduce current

EXCESSIVE PENETRATION

Excessive heat input	Reduce current and voltage. Increase travel speed.
Incorrect joint preparation	Reduce root gap. Increase root face.

SPATTER

Current too low	Increase current
Voltage too high	Decrease voltage
Acute torch to work angle	Maintain at 10° maximum to vertical
Incorrect inductance setting	Set at correct value
Work return clamp inefficient	Ensure clamp and cable are efficient

The above is guide only. Contact your Coregas representative for further advice.

Coregas line of shielding gases selection chart

Preference rating:
 1 = first
 2 = second

Note:
 a critical applications
 b non critical applications



Steels, mild and alloy	1	1	1	1	1	1	1
High deposition rates	1	1	1	1	1	1	1
All positions	1	2	2	2	1	2	2
Penetration	2	1	1	2	2	1	1
Rapid solidification	1	1	2	2	1	2	2
Hot arc	2	1	1	1	2	1	1
Flux cored wires	2	2	1	2	2	1	2
X-ray quality	1	1	1	1	1	2	1
Low spatter	1	1	2	2	1	2	1
Thin guage material	1	2	2	2	1	2	2
Rust/scale tolerance	2	1	1	1	1	1	1
Zinc coated steel	2	1	1	2	2	1	1
Galvanised coated steel	2	1	1	2	2	1	1
Stainless steels/duplex	zb						

SIX- AND TWELVE-PACKS

Cylinder packs, complete with pipeline systems, offer substantial savings for the larger user.

Ask your Coregas representative for details.

Safety in welding

Ventilation

- Ensure adequate ventilation in welding area.
- Use exhaust fans where necessary.
- Provide clean, dry air supply in confined spaces.

Helmets

- To be of approved types.
- To be fitted with filter lens of suitable shade.
- Space gasket to be fitted between front clear lens and filter lens.

Personnel protection

- Dark coloured clothing advised.
- Woollen materials preferable to synthetics or cotton.
- Cover body completely.
- Gloves are essential and must be dry.
- Wear robust footwear, not thongs, sandals etc.
- Screen the work to protect others from the arc flash.

Electrical

- Only licenced electricians to attend to electrical repairs.
- Ensure all cables are sound and free from defects.
- Ensure all electrical connections are efficient and tight.

Cleaning

- Do not use carbon tetrachloride or trichloroethylene (toxic). Use white spirit or acetone.

Location

- Ensure welding area is dry.
- Do not weld in wet locations.
- Ensure area is free of combustibles and flammable materials.



Coregas Pty Ltd
66 Loftus Road
Yennora NSW 2161
T: (02) 9794 2223
F: (02) 9794 2264
I: www.coregas.com

Adelaide

Telephone: (08) 8222 1111

Brisbane

Telephone: (07) 3375 3622

Melbourne

Telephone: (03) 9465 0488

Newcastle

Telephone: (02) 4967 3522

Wollongong

Telephone: (02) 4271 5455